

(2)【平沖隣】 状況写真

被災状況



工事の状況(R3.3月現在)



【全景】

- ・住家等被害：半壊 1戸
- ・人的被害：死亡者数 0人
- ・公共施設被害：市道 L=約40m



【工種】
工事完了

二級河川沼田川水系 平沖隣 災害関連緊急砂防工事 (三原市大和町椋梨)

施工:山陽建設株式会社

(1)2019.12 着工前



(2)2020.3 本堤掘削状況



(3)2020.4 本堤掘削完了



(4)2020.6 本堤工(ソイルセメント)①



(5)2020.7 本堤工(ソイルセメント)②



(6)2020.8 本堤工(ソイルセメント)③



(7)2020.9 本堤工(ソイルセメント)④



(8)2020.10 本堤工(ソイルセメント)完了



(9)2020.11 前庭保護工



(10)2020.12 取付護岸工



(11)2021.2 管理用道路工



(12)2021.3 完成

