

(2)【川尻地区】 状況写真

被災状況



工事の状況(R2.3月現在)



【全景】

- ・住家等被害：全壊 1戸  
半壊 1戸
- ・人的被害：死亡者数 0人
- ・公共施設被害：市道 L=約50m



【工種】  
工事完了

川尻地区 災害関連緊急急傾斜地崩壊対策工事 (尾道市向島町)

施工: 洋翔建設株式会社

(1) 2019.5 着工前



(2) 2019.6 伐採完了, シート養生



(3) 2019.7 仮設工状況①



(4) 2019.8 仮設工状況②



(5) 2019.9 法面掘削工(SSD工法)①



(6) 2019.9 法面掘削工(SSD工法)②



(7) 2019.10 法面掘削工③



(8) 2019.11 掘削完了



(9) 2020.1 法面工状況①



(10) 2020.2 法面工状況②



(11) 2020.3 完成

