

(3)【東川】 状況写真

被災状況



工事の状況(R4.3月現在)



【全景】

- ・住家等被害：全壊 1戸
- ・人的被害：死亡者数 0人
- ・公共施設被害：市道 L=約360m
白竜湖スポーツ村公園



【工種】
工事完了

二級河川沼田川水系 東川 災害関連緊急砂防工事 (三原市大和町和木)

施工：沼田建設株式会社

(1) 2019.8 着工前



(2) 2019.11 工事用道路施工



(3) 2020.1 本堤掘削



(4) 2020.2 本堤掘削完了



(5) 2020.3 本堤工(ソイルセメント)①



(6) 2020.8 本堤工(ソイルセメント)②



(7) 2020.9 本堤工(ソイルセメント)完了



(8) 2020.12 副堰堤工(Co打設)



(9) 2020.4 前庭保護工(Co打設)



(10) 2021.9 帯工(Co打設)



(11) 2021.12 流末水路工



(12) 2022.3 完成

