

(5)【河頭隣】 状況写真

被災状況



- ・住家等被害：全壊 1戸
- ・人的被害：死亡者数 0人
- ・公共施設被害：市道 L=約100m

工事の状況(R3.2月現在)



【全景】



【工種】
工事完了

二級河川沼田川水系 河頭隣 災害関連緊急砂防工事 (三原市大和町大草)

施工: 沼田建設株式会社

(1) 2019.11 着工前



(2) 2020.1 工事用道路施工①



(3) 2020.2 工事用道路施工②



(4) 2020.3 本堤掘削①



(5) 2020.4 本堤掘削②



(6) 2020.5 本堤工(ソイルセメント)



(7) 2020.6 本堤工(ソイルセメント)②



(8) 2020.7 本堤工(ソイルセメント)③



(9) 2020.8 本堤工(ソイルセメント)④



(10) 2020.10 前庭保護工①



(11) 2020.12 前庭保護工①



(12) 2021.2 完成

