

(6)【河頭隣1】 状況写真

被災状況



- ・住家等被害：半壊 1戸
- ・人的被害：死亡者数 2人
- ・公共施設被害：なし

工事の状況(R3.3月現在)



【全景】



【工種】
工事完了

二級河川沼田川水系 河頭隣1 災害関連緊急砂防工事 (三原市大和町大草)

施工:株式会社雲地建設

(1)2019.12 着工前



(2)2020.1 工事用道路完了




(3)2020.1 本堤掘削状況



(4)2020.2 本堤掘削完了



(5)2020.3 本堤工打設状況①



(6)2020.5 本堤打設状況②



(7)2020.6 本堤打設状況③



(8)2020.8 本堤打設状況④



(9)2020.9 前庭保護工①



(10)2020.12 前庭保護工②



(11)2021.2 管理用道路工



(12)2021.3 完成

