

(7)【善入寺川支川3隣】 状況写真

被災状況



- ・住家等被害：半壊 1戸
- ・人的被害：死亡者数 0人
- ・公共施設被害：市道 L=約20m

工事の状況(R2.12月現在)



【全景】



【工種】
工事完了

二級河川沼田川水系 善入寺川支川3隣 災害関連緊急砂防工事 (三原市本郷町善入寺)

施工:株式会社金光組

(1)2019.9 着工前



(2)2019.11 工事用道路施工状況



(3)2019.12 本堤掘削状況



(4)2020.1 本堤掘削完了



(5)2020.2 本堤打設状況①



(6)2020.4 本堤打設状況②



(7)2020.5 本堤打設完了



(8)2020.6 仕戻し工



(9)2020.7 仕戻し工完了



(10)2020.8 前庭保護工



(11)2020.10 管理用道路工



(12)2020.12 完成

