

(1)【潮見G地区】 状況写真

被災状況



- ・住家等被害：全壊 2戸
半壊 1戸
- ・人的被害：死亡者数 1人
- ・公共施設被害：なし

工事の状況(R2.2月現在)



【全景】



【工種】
工事完了

潮見G地区 災害関連緊急急傾斜地崩壊対策工事 (尾道市桜町)

施工: 洋翔建設株式会社

(1) 2019.4 着工前



(2) 2019.4 着工前



(3) 2019.7 法面掘削状況①



(4) 2019.8 法面掘削状況②



(5) 2019.9 法面掘削状況③



(6) 2019.10 法面工(ラス張工)状況



(7) 2019.11 法面工(吹付法砕工)状況



(8) 2019.12 法面工完了①



(9) 2019.12 法面工完了②



(10) 2020.2 完成

