

(11)【東五反田川隣】 状況写真

被災状況



工事の状況(R4.3月現在)



【全景】

- ・住家等被害：半壊 3戸
- ・人的被害：死亡者数 0人
- ・公共施設被害：市道 L=約900m
国道 L=約250m



【工種】
工事完了

その他水系 東五反田川隣 災害関連緊急砂防工事 (尾道市吉和町)

施工:株式会社タカマツ建設, 株式会社堀田組

(1)2019.6 着工前



(2)2020.2 工事用道路施工①



(3)2020.5 工事用道路施工②



(4)2020.6 工事用道路施工③



(5)2020.7 本堰堤掘削工



(6)2020.8 本堰堤打設状況①



(7)2020.10 本堰堤打設状況②



(8)2020.12 本堤工打設完了



(9)2021.2 副堰堤打設状況



(10)2021.6 取付護岸工



(11)2021.10 付替農道工①



(12)2022.3 完成

